

May 23, 2003

TO: Internal File

THRU: Daron R. Haddock, Permit Supervisor

FROM: Dana Dean, P.E./Senior Reclamation Hydrologist

RE: 2002 First Quarter Water Monitoring, Plateau Mining Corporation, Willow Creek Mine, C/007/038-WQ02-1

1. Was data submitted for all of the MRP required sites? YES ☐ NO ☒

Identify sites not monitored and reason why, if known:

The Permittee reported No Access at sites B261, B262, B271, B341, B342, B351, B352, B361, B362, B41, B263, B353, B331, and B331A. The Permittee cited unsafe road conditions as the reason.

The Permittee did not sample site B22-1 due to influence from surface runoff by adjacent snow melt.

2. On what date does the MRP require a five-year resampling of baseline water data.

See Technical Directive 004 for baseline resampling requirements. Consider the five-year baseline resubmittal when responding to question one above. Indicate if the MRP does not have such a requirement.

Resampling due date The Willow Creek Mine is in reclamation and does not have any resampling of baseline water data scheduled.

3. Were all required parameters reported for each site? YES ☐ NO ☒

Comments, including identity of monitoring site:

The Permittee/lab inadvertently omitted dissolved manganese from the parameter suite for B321 and B151 and total suspended solids from B151.

4. Were irregularities found in the data?

YES ☐

NO ☒

Comments, including identity of monitoring site:

5. Were DMR forms submitted for all required sites?

1st month, YES ☒ NO ☐

2nd month, YES ☒ NO ☐

3rd month, YES ☒ NO ☐

6. Were all required DMR parameters reported?

YES ☒

NO ☐

Comments, including identity of monitoring site:

7. Were irregularities found in the DMR data?

YES ☐

NO ☒

Comments, including identity of monitoring site:

8. Based on your review, what further actions, if any, do you recommend?

No Further actions are necessary.